## How to Calibrate PCT Touch

TOLL FREE: (888) 483-2418 • EMAIL: info@itechlcd.com • WEB: www.iTechlCD.com



## How to Calibrate PCT Touch

First step to set correct resolution in PC, and then try re-plug the USB cable for the touch (that will recalibrate the touch automatically), it' better reboot again to let the system detect correct touch driver on windows system.

## Use the following steps to calibrate your touch screen in Windows 7:

- 1. Click Start and then Control Panel, and next Hardware and Sound.
- 2. Under Tablet PC Settings, tap Calibrate the screen for pen or touch input.
- 3. On the Display tab, under Display options, tap **Calibrate** and then **Yes** to allow the program to make changes.
- 4. Follow the on-screen instructions to calibrate your touch screen.



TOLL FREE: (888) 483-2418 • EMAIL: info@itechlcd.com • WEB: www.iTechlCD.com