


### Assembly - Step 4:



- Set the training table height on each leg assembly by unscrewing and sliding the leg to the desired position.
- Re-insert screws to secure



## Instructions / Directions

### 36" Training Table # 5500-3-00X-XX



Distributed by : i-Tech Company LLC

TOLL FREE: (888) 483-2418

• EMAIL: [info@iTechLCD.com](mailto:info@iTechLCD.com)

• WEB: [www.iTechLCD.com](http://www.iTechLCD.com)

## Tools Needed:




Screw Driver

## Included:



## Assembly - Step 1:




- Position table top with smooth surface facing down
- Line up leg assemblies with pre-drilled hole pattern (note - shorter side of legs face the back of the table)
- Fasten to table top with 1/4" screws

\* If installing the Cable Management Enclosure leave out back two screws in the legs

2

## Assembly - Step 2:


\*If installing the Cable Management Enclosure, proceed to mount that to the modesty panel before assembling the panel to the training table



- Attach modesty panel to the back edge of the right and left leg assembly. (Make sure the grommet opening is closest to the work surface)
- Fasten with 1/4" screws.

\*\* If not installing the Cable Management Enclosure—fill in additional threaded holes in modesty panel with additional screws.

## Assembly - Step 3:



- Insert levelers into the threaded inserts in the bottom of the leg assemblies.
- Insert end caps into base of each leg kit.

3